

HARTZELL PROPELLER, INC.
PIQUA, OHIO

BULLETIN NO. 58

"CAA APPROVED"

March 12, 1958

SUBJECT: Overhaul of Hartzell Propellers - Replacement of Split Rings.

GENERAL: It is recommended that all split rings, parts A-159 and A-1331 be replaced in all Hartzell constant speed propellers at each overhaul as standard procedure.

The reasons for this are:

- (a) 500 to 1000 hours will result in enough wear to justify replacement.
- (b) Current production rings are improved from several standpoints.

This bulletin supersedes Bulletin No. 52 calling for modification of the rings at overhaul.

Current production A-159 split rings are identified with the letter "N". No identification is inscribed on A-1331 rings as they are all current production.