



SERVICE LETTER

No. 243

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

February 8, 1955

TO: All Distributors, Dealers, Owners and Operators

SUBJECT: PA-22 Engine Mount

MODELS AFFECTED: All PA-22's

We have received three official reports that fatigue cracks have appeared in the PA-22 engine mounts in the vicinity of the welds at both the firewall and the engine attachment points.

It is requested that each PA-22 owner inspect his engine mount at his earliest convenience, to determine whether or not there is any evidence of fatigue cracks in the aforementioned areas. If cracks are present, effective repairs should be made in accordance with the CAM-18.

Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in cursive script that reads "R. Boardman".

Rolland Boardman
Service Manager

RB:mh
