



SERVICE LETTER

No. 348

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

December 9, 1960

TO: Distributors, Dealers, Owners and Certified Service Centers

SUBJECT: Replacement of Airspeed Indicators

MODELS AFFECTED: PA-22-108 Colt Aircraft - Serial Nos. 22-8000 to 22-8017
inclusive

DATE OF COMPLIANCE: Prior to but not later than next 25 hours of operation

The airspeed indicators installed on the subject aircraft, as indicated by the above serial numbers, have been recalibrated. A new airspeed indicator, part number 11339-16, is now available and will be forwarded by automatic distribution. This replacement is mandatory.

The airplane flight manual has been revised to incorporate this change and a new copy will be forwarded at the same time as the airspeed indicators. The obsolete flight manual must be destroyed.

A compliance card will accompany the new airspeed indicator and must be returned to the Service Department, indicating date of compliance.

The removed airspeed indicators must be returned for credit on duly executed Warranty and Credit Claim forms.

Very truly yours,

PIPER AIRCRAFT CORPORATION


Wes Holmes
Service Manager

WH:pz
