



# SERVICE LETTER

No. 362B

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

December 11, 1974

---

(Supersedes and voids Piper Service Letter No. 362A, dated December 12, 1973)

Reason for Revision:

Revision to PA-12 Super Cruiser Serial Numbers Affected section; Fuselage Fabric Trim Strip Installation Kit, Piper part number 760 799, cannot be installed on PA-12, serial numbers 12-1 to 12-2903 incl., due to the type of windshield installed in these aircraft.

Subject:

Modification of Windshield Top Attachment

Models Affected:

PA-12 Super Cruiser

PA-14 Family Cruiser

PA-15 Vagabond

PA-16 Clipper

PA-17 Vagabond Trainer

PA-20 Pacer

PA-22 Tri-Pacer

Serial Numbers Affected:

12-2904 to 12-2906 incl., 12-2908 to 12-2910 incl., 12-2913, 12-2916, 12-2918 to 12-2924 incl., 12-2926 to 12-2949 incl., 12-2951 to 12-3027 incl., 12-3029 to 12-3900, and 12-3904 to 12-4036 incl.

14-1 to 14-11 incl.

15-1 to 15-388 incl.

16-1 to 16-137 incl.

17-1 to 17-215 incl.

20-1 to 20-1121 incl.

22-1 to 22-7630 incl.

Compliance Time:

Recommended at the next regularly scheduled inspection.

Purpose:

To provide material and instructions to reinforce the area where the fabric attaches to the fuselage under the windshield top and/or directly over the rear edge of the windshield top attachment channel on the above referenced aircraft. The attached sketch illustrates this area.

Installation of the modification kits described in Material Required, below, eliminates the requirement for the inspection of this area described in Piper Service Bulletin No. 174B, dated November 30, 1961, and F.A.A. Airworthiness Directive No. 61-6-6.

Instructions:

Contained in Fuselage Fabric Trim Strip Installation Kits, Piper part numbers 754 404 and 760 799 (reference Material Required, below).

---

Material Required:

1. Applies to PA-15, PA-16, PA-17 and PA-20 aircraft listed above, and PA-22 aircraft serial numbers 22-1 to 22-7630 incl.: One (1) each per aircraft Fuselage Fabric Trim Strip Installation Kit, Piper part number 754 404, at \$ suggested unit retail price.
2. Applies to PA-12 and PA-14 aircraft listed above: One (1) each per aircraft Fuselage Fabric Trim Strip Installation Kit, Piper part number 760 799, at \$4.58C suggested unit retail price.

Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:


This Service Letter is effective upon receipt.

Summary:

Please contact your Piper Field Service Facility to make arrangements for procurance and installation of the above referenced modification kits. Installation of these kits eliminates the repetitive inspection requirements as denoted in Piper Service Bulletin No. 174B and F.A.A. Airworthiness Directive No. 61-6-6.

NOTE

Affected aircraft that have previously complied with the provisions of Piper Service Letter No. 362, dated November 3 1961 and Service Letter No. 362A, dated December 12, 19 are not required to comply with this Service Letter.



***Service Letter No. 362B***