

## MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved
OMB No 2120-0020
For FAA Use Only

Office Identification

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions
and disposition of this form. This report is required by law (49 U.S.C. 1421). Failure to report can result in a civil penalty not to exceed \$1,000
for each such violation (Section 901 Federal Aviation Act of 1958).

for eac	ch such violation (	Section	on 901 Federal Avi	ation A	ct of	1958).				,	, , , , , , , , , , , , , , , , , , ,	
	Make						Model PA-22-135					
1. Aircraft	Serial No.	Serial No. 22-1646				Nationality and Registration Mark N3383A						
2. Owne	1	Name (As shown on registration certificate Frank P. Sperandeo III				Address (As shown on registration certificate)  15841 Pear Cir. Fayetteville, AR 72704						
					2	For FAA Use	Only					
					<b>J.</b>	TOTTAL GE	THE MEES	DAM DATA IDENTIFIED HERE REMENTS AND IS APPROVE UBJECT TO CONFORMITY IN	EIN POUPLIES WI EVONLY FOR THE PECTION EVILAP FLATING	ITH APPLICABLE AIRW ABOVE DESCRIZED VERYOUTHORIZED ECTOR	CRITH-	
					4,	Unit Identifica	ition			5. Type		
Unit		Make				Model		Serial N	lo.	Repair	Alteration	
AIRFRAME	•	As desc				cribed in Item 1 above)					X	
POWERPL	ANT		•			·	. , ,					
PROPELLE	ER					TANK TO THE						
APPLIANC	Type  Manufactur	er		of of				(H ) (H ) (U )				
^ ^====	u's Nome and Ada			: · · · · ·	1	nformity State						
A. Agenc	y's Name and Add	iress	, ,		X	Kind of Agend U.S. Certificat			C. Cert	ificate No.		
K. V. Turney 17654 Marshall St. Garfield, AR 72732				_	Foreign Certificated R	ertificated Mechanic d Repair Station			1464298			
have	tify that the repair	and/o	or alteration made to noce with the require correct to the best	ements	of Pa	art 43 of the U	em 4 above .S. Federa	and described on I Aviation Regulat	the reverse ions and th	or attachment the inform	nts hereto lation	
Date				-	Sign	nature of Auth	orized Ind	lividual				
5/18/86			4 V Leunes									
				7. Ap	prova	for Return 1	o Service					
Pursuan Adminis	it to the authority trator of the Feder	giver	n persons specifie iation Administrati	d belov on and	v, the	unit identific		4 was inspected REJECTED	in the man	mer prescribe	ed by the	
	FAA Flt. Standards Inspector		Manufacturer	X	Inspe	ection Authori	zation	Other (Specify,	)	*		
1 1	FAA Designee		Repair Station			on Approved buda Airworthin		t		_	ļ	
ate of Ap	proval or Rejection	n	Certificate or Designation No.		Sign	ature of Auth	orized Indi	vidual				
5/18/96				8. It Junes								

## NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8.	Description	of Work Acc	omplished
----	-------------	-------------	-----------

(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

- 1. Installed two, 1.5" x 3.0", 12VLT/.25AMP Courtesy Lights on underside of wing root fairings. (Left and right.)
- 2. Installed a 2 amp Potter-Brumfield circuit breaker #W23X1A1G2, and one toggle switch, SPST, AN 3031-2, MS 35058-22.
- 3. All wiring installed in accordance with AC43.13-1A Sec 3, Fig. 11-7.
- 4. No significant change of existing weight and balance of aircraft.

## RECEIVED

MAY 2 8 1996

FAA EW-FSDO-11

01		7	_		
0.3	-	MGR			_
02	1		_	$AH^{-}$	
03	<b>†</b>	SPN	7	+	_ 1
11.3	_		21	[42]	$\neg$
14		(3PM)			
				133	- 1
0.5		10	7		
	/	_CS T		14	- 1
06			i	15	$\dashv$
	/	ASAL		3.7	- 1
117			_ 1/	16	$\neg$
100		ASAZ	-		
UB		20.12		71	7
Orth		157			
OTHE	R			18	7
			, -	9	-1
				וכי	