
MB#2703 Burnett M. Schultz 6611 Imlach Way Anchorage, AK 99502-2159

JOTICE

inges shall be entered in the appropriate aircraft record, vious alterations to assure continued conformity with the

- 8. DESCRIPTION OF WORK ACCOMPLISHED (If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)
 - 1. Altered both wing tips by removing wing bows and last rib. Spread both upper and lower spar caps and inserted 1/8" aluminum plates between them. Fabricated new(#1) leading edges. Fabricated false spar to accommedate the extention of each aileron and the last out board ribs. Installed ribs(#2) #7-12046-04 (inboard) and new(#3) #7-12046-07 (outboard). Installed (#5) compression fitting between inboard and outboard ribs and attached(#6) aileron hanger aft of the fitting. Installed(#4) Ferguson tip by Sullivan(Maule type). Extended both ailerons 24" with an aileron spar splice and added an extra hinge to each aileron to attach on #6 hanger.



N1805P / 22-2584

ADDITIONAL SHEETS ARE ATTACHED

12-91