AIRCRAFT OPERATING LIMITATIONS WITH DOOR REMOVED

This aircraft may be flown with not more than one cabin door removed for the purpose of Photography , provided the aircraft is operating in accordance with the applicable Federal Aviation Regulations and the following limitations:

- 1. Maximum speed not to exceed any of the following: THE MANEUVERING SPEED; 70 PER CENT MAXIMUM LEVEL FLIGHT SPEED; 70 PER CENT MAXIMUM STRUCTURAL CRUISING SPEED.
- 2. Acrobatic maneuvers are not permitted.
- Maximum yaw angle 10°; maximum bank angle 15°.
- 4. An FAA approved safety belt installation must be provided and worn by each occupant.
- 5. All occupants must wear parachutes when conducting intentional parachute jumping and sky diving operations.
- Smoking not permitted with door removed.
- 7. When operations other than intentional parachute jumping and sky diving are conducted, a suitable guardrail or equivalent safety device must be provided for the doorway.
- 8. All loose articles must be tied down or stowed.
- 9. No baggage may be carried.
- io. Parachutist's static lines must be kept free of pilot's controls and control surfaces.
- 11. Operations limited to VFR conditions.
- 12. Cabin door hold-open clips installed on wing brace struts and/or under surface of wing must be removed prior to conducting parachute jumping or sky diving operations.
- 13. When intentional parachute jumping, sky diving, or other specified operations are being conducted, the pilot at the controls must hold at lease a private pilot certificate.
- 14. This aircraft shall not be operated in solo flight by the holder of a student pilot certificate with a door removed.
- Operation of this aircraft for any other purpose than for which it is certificated, with a door removed, is prohibited.
- 16. The following placard must be placed on the instrument panel in full view of the pilot: FOR FLIGHT WITH DOOR REMOVED, SEE AIRCRAFT OPERATING LIMITATIONS WITH DOOR REMOVED.
- 17. A copy of these limitations must be carried in the aircraft when flight operations are conducted with the door removed.

18.	These operating	limitations	are	a	part o	£	the	airworthiness	certificate.
-----	-----------------	-------------	-----	---	--------	---	-----	---------------	--------------

DATE: 02-24-39 Seeky British

FAA INSPECTOR (AIRWORTHINESS) SO FSDO 09, Birmingham, Alabama