

PIPER REPORT NO. 790

CAA Approved  
Approval Basis CAR 3 and 410  
December 29, 1952  
Revised September 30, 1954

WINTERIZATION SUPPLEMENT TO

PIPER PA-18 "135", PA-18A "135", PA-18 "150",  
PA-18A "150", PA-20 "135", PA-22 "135" AND  
PA-22 "150" AIRPLANE FLIGHT MANUAL

Airplane Identification No. \_\_\_\_\_ (STANDARD)

Note: This Supplement must be attached to the C. A. A.  
Approved Airplane Flight Manual when the  
alternate equipment specified below is installed.  
Information contained herein supplements or  
supersedes corresponding information of the  
basic manual.


Alternate Equipment - Piper Winterization Kit

I. Installation Instructions

Winterization Kit consists of oil radiator cover, Piper  
No. 14793, installed on the front of the oil radiator,  
Placard, Piper No. 14090, installed in the cockpit in  
front of and in full view of the pilot, and Winterization  
Supplement, Piper Report No. 790, attached to the  
C. A. A. Approved Airplane Flight Manual.

II. Limitations

Winterization Kit for use on airplanes operating in  
outside air temperature below 40°F. Kit must be  
removed when operating in temperatures above 40°F.

  
\_\_\_\_\_  
J. W. McNary  
Asst. Chief Engineer  
Piper Aircraft Corporation  
DMCR 1-1