

IMMEDIATE ACTION

**SERVICE**



**BULLETIN**

NUMBER 135

March 29, 1955

**SUBJECT: Fuel Selector Valve Pointer**

**MODELS AFFECTED: All PA-20 and PA-22**

There is a possibility that the pointer on the fuel selector valve may have been installed incorrectly on some of the Model PA-20 and PA-22 airplanes. Conceivably, the pointer could rotate with the result that there would be a false indication as to which tank the supply of fuel was coming from.

It is requested that all fuel selector valve handles be inspected and that, if necessary, the handles be disassembled and reassembled in accordance with the sketch on the reverse side of this letter.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.

