



SERVICE LETTER

No. 258

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

November 30, 1955

TO: All Distributors, Dealers and Owners

SUBJECT: PA-22 Fuel Tank Cap

MODELS AFFECTED: All PA-22 Airplanes

Recently the C. A. A. issued an Airworthiness Directive No. 55-22-3 relative to the fuel tank caps on all Piper PA-22 aircraft.

The identification of both types of cap seems to be quite adequate in the directive, however, for the benefit of those who are still unable to distinguish the old from the new, we have provided sketches on the reverse side of this letter.


Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in cursive script, appearing to read "R. Boardman".


Rolland Boardman
Service Manager

RB:gh



BROWN
FIBRE GASKET

OLD STYLE



BLACK
RUBBER GASKET

NEW STYLE
454 039

PA-22 FUEL CAPS	
SKETCH "A"	No. 258
PIPER AIRCRAFT CORPORATION	
LOCK HAVEN, PENNSYLVANIA	