



SERVICE LETTER

No. 355

Customer Services

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

February 23, 1961

TO: All Distributors, Dealers, Piper Certified Service Centers and Owners

SUBJECT: Stainless Steel Control Cables

We are pleased to announce that stainless steel control cables are once again available for our aircraft. These cables are of new design and this letter must in no way be construed to mean that the older type stainless steel control cables referred to in Service Bulletins Numbers 181 and 182 - (export) may be used.

The following listing indicates the part numbers of the old type stainless steel control cables and the replacement cables of new design which may be used:

| <u>Old Type Stainless Steel Control Cable Part Number</u> | <u>New Type Stainless Steel Control Cable Part Number</u> |
|---|---|
| 40123-36 | 14300-12 |
| 40123-37 | 14300-13 |
| 40123-38 | 14300-14 |
| 40123-39 | 14300-15 |
| 40123-40 | 14300-16 |
| 40123-41 | 14300-17 |
| 40123-42 | 14300-18 |
| 40123-44 | 14300-19 |
| 40123-45 | 14300-20 |
| 40123-71 | 14300-21 |
| 40123-72 | 14300-22 |
| 40123-82 | 14300-23 |
| 40123-83 | 14300-24 |
| 40123-84 | 14300-25 |
| 40123-85 | 14300-26 |
| 40123-86 | 14300-27 |
| 40123-87 | 14300-28 |
| 40123-94 | 14300-29 |
| 10870-02 | 10870-13 |
| 10870-09 | 10870-14 |
| 10870-10 | 10870-15 |
| 10870-11 | 10870-16 |
| 10870-12 | 10870-17 |
| 10865-04 | 10865-05 |
| 13745-02 | 13745-03 |

(over)

Old Type Stainless
Steel Control CablePart Number

12794-03
 13271-02
 11527-03
 12515-02
 12515-04
 13108-03
 13109-04
 13109-05
 13109-13
 13109-15
 10869-02
 10869-05
 12514-02
 12526-03
 11641-05
 61181-00
 61181-02
 61181-03
 61181-04
 61181-05
 61181-06
 61181-07
 61181-08
 61181-09
 61181-10
 61181-11
 61181-12

New Type Stainless
Steel Control CablePart Number

12794-04
 13271-03
 11527-04
 12515-05
 12515-06
 13108-11
 13109-16
 13109-17
 13109-18
 13109-19
 10869-03
 10869-08
 12514-03
 12526-05
 11641-08
 61181-13
 61181-14
 61181-15
 61181-16
 61181-17
 61181-18
 61181-19
 61181-20
 61181-21
 61181-22
 61181-23
 61181-24

Stainless steel control cables will not normally be carried in stock; however, they can be readily manufactured upon request.

We also want to call your attention to the fact that the appropriate parts catalogs covering stainless steel control cables will not be changed at the present time and it will, therefore, be necessary for you to accomplish your own revision to the appropriate parts catalogs. Catalogs primarily affected are those used for the Models PA-18-18A, PA-20 and PA-22 series aircraft.

Very truly yours,

PIPER AIRCRAFT CORPORATION


 Wes Holmes
 Service Manager

WH:dt