

SERVICE



LETTER

Service Letter No. 154

July 12, 1950

(Supersedes Service Letter No. 141)

Dated April 4, 1950

To: All Distributors

Subject: Addition of Felt Strips on the Wing Tank Cover in
Model PA-11, serial 11-1 and up
Model PA-16, serial 16-1 and up
Model PA-18, serial 18-1 to 18-113 inclusive
Model PA-20, serial 20-1 to 20-152 inclusive

Due to the production variations, it has been noted that the clearance on some airplanes between the reinforcements on the gas tank cover and the gas tank itself, is insufficient. It is recommended that the gas tank covers on the listed PA-11's, PA-16's, PA-18's and PA-20's be removed and strips of felt be cemented over the fore and aft reinforcements on the covers.

It is suggested that felt of specification SAE-F-50, or its equivalent, be used. The size of the felt strips should be 1/2" wide and 1/16" thick.

Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in dark ink, appearing to read "R. Boardman", is written over the typed name.

Rolland Boardman
Service Manager

RB:gh

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA.. U. S. A.