



SERVICE LETTER

No. 423

Customer Services

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.
May 5, 1964

TO: Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Muffler and Tailpipe Support Kits

MODELS AFFECTED: PA-22-108 Colts, Serial Numbers listed below:

MUFFLER SUPPORT KIT NO. 756 803
Serial Numbers 22-8000 to 22-9848 incl.

TAILPIPE SUPPORT KIT NO. 756 804
Serial Numbers 22-8000 to 22-9204 incl.

This Service Letter is to advise that a muffler support kit, No. 756 803, and a tailpipe support kit, No. 756 804, are available for installation on the subject aircraft.

These supports are applicable to the PA-22-108 Colts within the serial numbers listed above and it is recommended that they be installed on these aircraft as the additional support will be instrumental in extending the service life of the exhaust system. See sketch on the reverse side of this letter for installation details.

Muffler support kit No. 756 803, suggested retail price \$8.86, and tailpipe support kit No. 756 804, suggested retail price \$2.82, may be ordered through your nearest Piper distributor or dealer.

Very truly yours,

PIPER AIRCRAFT CORPORATION

W. C. Holmes
W. C. Holmes
Service Manager

WCH:jf

(Over)

Tube Assy. Muffler
Support 15270-00

Bolt AN3-5A
Nut AN365-1032C
Washer AN960-10

Tube Assy. 15269-00
Muffler Support
1/2" Min. Clearance
between tube and
landing gear support

Use existing
washers

Clamp 80002-74

Washer AN960-416
Clamp 80002-74

Clamp 10466-33

Bolt AN3-5A
Nut AN364-1032C
Washer AN960-10

Cap Screw

1/4 - 20 UNC 2A x 5

Bolt AN3-6A
Nut AN365-1032C
Washer AN960-10

Tube Assy.
Tail pipe support 11962-00

Service Letter

423